



## Figures

113




FIG. 1




FIG. 2




FIG. 3

Contact speed setup Automatic shifting speed for mouse contact mode <input type="checkbox"/> Slow <input type="checkbox"/> Normal <input checked="" type="checkbox"/> Fast	shifting direction precision <input type="checkbox"/> Normal (Up/down/left/right)  <input type="checkbox"/> (1/8)  <input type="checkbox"/> (1/16)  <input type="checkbox"/> Precise (all-direction) <input type="checkbox"/> Customized range ___/360
<input type="checkbox"/> Default value	

FIG. 4

3/2




FIG. 5